



Ambient Air Concentration of Gases
NH₃, NO₂ and SO₂

Site	Date On	Date Off	NH ₃	NO ₂	SO ₂
			µg/m ³	µg/m ³	µg/m ³
Site 5 - Burrup Road	No new results received to date				
Site 6 - Water Tanks					
Site 7 – Hearsons Cove					

Notes:

(1) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd
Air Quality Monitoring Report
March 2024

03/05/2024 650-200-REP-YPN-0078 Rev 0

Airborne Particulate Concentration
Total Suspended Particulates (TSP)

Period Start Date ^{(1),(2)}	Site 5 (Burrup Road) TSP	Site 6 (Water Tanks) TSP	Site 7 (Hearsons Cove) TSP
	$\mu\text{g}/\text{m}^3$	$\mu\text{g}/\text{m}^3$	$\mu\text{g}/\text{m}^3$
31-Jan-24	59	59	58
06-Jan-24	84	78	75
12-Feb-24	48	61	50
18-Feb-24	43	46	39

Notes:

- (1) The date is the date that sampling commenced.
- (2) The Low Volume Air Sampler unit runs for a nominal 24 hours.
- (3) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd
Air Quality Monitoring Report
March 2024

03/05/2024 650-200-REP-YPN-0078 Rev 0

**Deposited Dust - Total Dust Deposition per Month
Insoluble and Soluble Fraction**

Site 5 - Burrup Road		Date Deployed	29/12/2024
		Date Collected	31/01/2024
Parameter	Unit	Limit of reporting	
Soluble solids	g/m ² /month	0.7	1.2
Insoluble solids	g/m ² /month	0.8	1.2

Site 6 - Water Tanks		Date Deployed	29/12/2024
		Date Collected	31/01/2024
Parameter	Unit	Limit of reporting	
Soluble solids	g/m ² /month	0.7	1
Insoluble solids	g/m ² /month	0.8	1.2

Site 7 – Hearsons Cove		Date Deployed	29/12/2024
		Date Collected	31/01/2024
Parameter	Unit	Limit of reporting	
Soluble solids	g/m ² /month	0.7	0.7
Insoluble solids	g/m ² /month	0.8	1.8

Notes:

(1) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.